

Issue } 14-07-22
Stand }





3 611 C22 000
Issue
Stand } 14-07-22

Fig./Abb. 1

This technical drawing is an exploded view of a mechanical assembly, likely a pump or valve component. It shows various parts arranged in a linear sequence from left to right. The parts are identified by numbers in circles or plain text. Key components include a large threaded fitting (21, 22), a series of O-rings and seals (143, 144, 23, 25, 26, 28, 168, 153, 24), a central shaft or piston rod (820, 166, 158, 157, 165, 841), and a large cylindrical housing (35). Other parts like springs (44, 52), washers (37, 44, 99), and various nuts and bolts (95, 54, 853) are also shown. The diagram is set against a background with diagonal lines, and a large 'E' is visible near the center.

★ mit Loctite 222 sichern
secure with Loctite 222

Diagram of the Bosch brushless motor assembly, showing the motor housing (38) and the brushless motor (125).



● = Pos. 899 1 600 A00 4E6 ohne Fettube
1 600 A00 4E6 without grease tube