

Lista Piese BCG6L8F1S POLIZOR UNGHIULAR 1

Artic ol	Numarul Piese de Schimb	Cant.	Descriere Piesa	Descriere Generala	Alte informatii	Instructiuni de reparatie	Piete
1	NA516866	1	MÂNER SA			No	QW
2	90516498	2	ARC			No	QW
3	NA359124	2	CAPAC			No	QW
4	NA152865	1	GLISOR			No	QW
5	NA411520	1	ARC			No	QW
6	NA638969	7	ŞURUB		ST 3.5X20	No	QW
7	NA374122	1	MANŞON			No	QW
8	90532404	1	LAGAR			No	QW
9	NA575174	1	STATOR SA			No	QW
10	NA421794	1	ROTOR SA			No	QW
11	N505694	1	PINION			No	QW
13	N579741	1	BUTON			No	QW
14	NA605986	1	ARC			No	QW
15	N638660	1	INEL			No	QW
16	NA632264	1	CARCASA ANGRENAJ SA			No	QW
17	NA517219	1	AX			No	QW
18	N529724	1	SAIBA			No	QW
19	N505684	1	ANGRENAJ			No	QW
20	N611316	2	ŞURUB			No	QW
21	N529735	1	INEL			No	QW
22	N505684	1	ANGRENAJ			No	QW
23	N598827	3	ŞURUB			No	QW
24	NA426058	1	CAPAC			No	QW
25	N611227	1	FLANŞĂ			No	QW
26	N611235	1	FLANŞĂ			No	QW
27	NA381353	1	GARA SA			No	QW
29	NA575775	1	PARTE MÂNER SA			No	QW
30	N655360	1	CHEIE			No	QW
31	NA505272	2	ŞURUB			No	QW
801	N495279	1	SAC			No	QW
821	NA553971	1	ETICHETA DE CLASIFICARE			No	QW
866	N726529	1	BATERIE 18V - 4.0AH - 72WH	BL4018-XJ		No	QW

Lista Piese BCG6L8F1S POLIZOR UNGHIULAR 1

Artic ol	Numarul de Schimb	Piese Cant.	Descriere Piesa	Descriere Generala	Alte informatii	Instructiuni de reparatie	Piete
871	90634971	1	INCARCATOR SA	BDL2018S1B-QW - 8-20		No	QW